GENERAL SECRETARIAT

Notification dated 23rd November 1945.

No. T. 1435—R. T. 7-45-8. The following are republished for general information.

3379 MAHOMED ISMAIL SHERIFF. *Gl. Secy.*

WAR TRANSPORT DEPARTMENT.

NOTIFICATIONS.

New Delhi, the 13th August 1945.

No. 52-LPC(9)—45-Edelmann. In exercise of the powers conferred by sub-clause (1) (*b*) of clause 4 of the Motor Vehicle Spare Parts Control Order, 1944, and in supersession of all previous orders on the subject, the Central Government are pleased to specify for the purposes of the said clause the maximum retail sale price of 'Edelmann' products as detailed in the schedule annexed hereto.

2. These prices shall take effect from 5th September 1945.

SCHEDULE.

E. EDELMANN & Co., U.S.A.

Sl. No.	Part No.	Description	Make of vehicle for which suitable.	Year model	Maximum retail sale price.
1	2	3	4	5	6
					Rs. a. p.
1	300Z	Fuel line or feul pipe ...	Ford V8 ...	1932/40	2 5 0
2	301Z	Ditto	Ford V8 ...	1933	2 5 0
3	302Z	Ditto	Ford V8 ...	1932/33	2 5 0
4	312Z	Ditto	Chevrolet ...	1935/40	2 14 0
5	316Z	Ditto	Ford 4 Cy. ...	1932/34	2 9 0
6	317Z	Ditto	Ford Truck ...	1932/34	4 9 0
7	320Z	Ditto	Auburn ...	1935/36	4 4 0
8	328Z	Ditto	Chrysler, Desoto, Dodge...	1937	3 2 0
9	330Z	Ditto	Dodge ...	1932/33	3 7 0
10	332Z	Ditto	Chrysler, Desoto Dodge, and Plymouth.	1938/41	3 11 0
11	333Z	Ditto	Graham ...	1934/37	4 9 0
12	336Z	Ditto	Packard ...	1933/34	4 9 0
13	338Z	Ditto	Do ...	1935/36	4 4 0
14	340Z	Ditto	Essex 6 Cy., Terraplane 6 Cy.	1932/36	4 4 0
15	341Z	Ditto	Essex 8 Cy., Terraplane 8 Cy. Hudson 8 Cy. ...	1933 1934	4 4 0
16	342Z	Ditto	Hudson 6, 8, 112 ... Terraplane 6 ...	1935/40 1937/38	4 4 0
17	346Z	Ditto	Hupmobile ...	1933/34	4 9 0
18	348Z	Ditto	Oldsmobile ...	1937/39	3 2 0
19	349Z	Ditto	Do ...	1937/41	3 7 0
20	353Z	Ditto	Do ...	1935/36	3 7 0
21	355Z	Ditto	Nash ...	1934	4 4 0
22	360Z	Ditto	Desoto, Chrysler ... Dodge, Plymouth ..	1932/35	3 11 0
23	361Z	Ditto	Plymouth Desoto ...	1931	3 11 0
24	362Z	Ditto	Plymouth ...	1932/41	3 2 0
25	364Z	Ditto	Dodge & Plymouth ...	1936	3 11 0
26	366Z	Ditto	Pontiac ...	1933/34	3 2 0
27	368Z	Ditto	Do ...	1937/38	3 2 0
28	370Z	Ditto	Studebaker ...	1934	3 7 0
29	375Z	Ditto	Reo Truck ..	1933/36	4 9 0
30	377Z	Ditto	Nash ... Studebaker ...	1935/37 1937/41	3 2 0
31	385Z	Ditto	Willys ...	1933/36	4 0 0
32	386Z	Ditto	Do ...	1933/36	3 7 0
33	390Z	Ditto	Universal for 3/16" O.S. Copper tubing ...	...	2 14 0
34	391Z	Ditto	Universal for ¼" O.S. ... Copper tubing ...	...	3 7 0
35	B-60	1/4" Petrol pipe sleeve ...	Universal ...	...	0 1 0
36	B-60	3/16" Petrol pipe sleeve ...	Do ...	...	0 1 0
37	B 60	5/16" Petrol pipe sleeve ...	Do ...	...	0 1 3
38	B-61	3/8" Petrol pipe nuts... ...	Do ...	...	0 5 0
39	B-61	5/16" Petrol pipe nuts ...	Do ...	...	0 4 0
40	B-61	1/4" Petrol pipe nuts... ...	Do ...	...	0 3 0
41	B-61	3/16" Petrol pipe nuts ...	Do ...	...	0 3 0
42	B5-203	5/16"×1/8" cock	Do ...	...	3 10 0
43	B-329	Ditto	Do ...	...	4 7 0
44	B-429	Ditto	Do ...	...	4 2 0
45	B9 64	5/16" Tees	Do ...	...	1 10 0
46	B9-64	1/4" Tees	Do ...	...	1 8 0
47	B4 68	5/16"×1/8" straight connection ...	Do ...	...	0 11 0
48	B5-69	1/4"×1/8" Elbow	Do ...	...	0 14 0
49	B-69	5/16"× /8" Elbow	Do ...	...	1 1 0
50	B5 69	1/4"×1/4" Elbow	Do ...	...	1 0 0

No. 52-LPC (10)/45-King Quality.—In exercise of the powers conferred by sub-clause (1)(*b*) of clause 4 of the Motor Vehicle Spare Parts Control Order, 1944, and in supersession of all previous orders on the subject, the Central Government is pleased to specify for the purposes of the said clause the maximum retail sale prices of 'King Quality' products as detailed in the schedule annexed hereto.

2. These prices shall take effect from 5th September 1945.

SCHEDULE.

KING QUALITY PRODUCTS CO., U.S.A.

Sl. No.	Part No	Description	Make of vehicle for which suitable	Year model	Maximum retail sale price			
1	2	3	4	5	6			
					Rs.	a.	p.	
1	30	Piston ring set ...	Ford V8 ...	1937/40	15	10	0	Set
2	43	Ditto ...	Chevrolet ...	1934/36	14	15	0	,,
3	81	Ditto ...	Do ...	1934/40	14	15	0	,,
4	515	Ditto ...	Dodge ...	1934/40	34	5	0	,,
5	540	Ditto ...	International ...	1937/40	30	15	0	,,
6	543	Ditto ...	Ford V8 ...	1939/41	21	7	0	,,
7	564	Ditto ...	Oldsmobile Trk. ...	1939/40	34	5	0	,,
8	584	Ditto ...	G.M.C. Trk. ...	1941	24	10	0	,,
9	1501(Subst. 573)	Ditto ...	Ford V8 ...	1937/40	26	10	0	,,
10	P-214AX	Piston semi-finished with pin ...	Dodge ...	1934/40	23	2	0	
11	P-259AX	Ditto ...	Ford Car & Trk. ...	1937/40	10	9	0	
12	P-260AX	Ditto ...	Do ...	1937/40	10	7	0	
13	P-280AX	Ditto ...	Ford Trk. ...	1939/40	10	9	0	
14	P-1184X	Ditto ...	Chevrolet Car ...	1937/40	12	3	0	
15	P-1204X	Ditto ...	Chevrolet Trk.	1937/40	12	3	0	
16	P-1207X	Ditto. ...	International ...	1937/39	9	11	0	
17	P-214AX	Piston finished with pin ...	Dodge ...	1934/40	27	3	0	
18	P-259AX	Ditto ...	Ford Car & Trk. ...	1937/40	10	9	0	
19	P-260AX	Ditto ...	Do ...	1937/40	10	7	0	
20	P-280AX	Ditto ...	Ford Trk. ...	1939/40	10	9	0	
21	P-1184X	Ditto ...	Chevrolet Car ...	1937/40	13	14	0	
22	P-1204X	Ditto ...	Chevrolet Trk. ...	1937/40	13	14	0	
23	P-1207X	Ditto ...	International ...	1937/39	10	13	0	
24	PX-10	Piston skirt expander ...	Dodge Trk. ...	1934/40	2	12	0	
25	WB-1S24	Piston pin bushing ...	Dodge ... 1934/40 Chrysler ... 1933/40 Desoto ... 1941/40		0	11	0	
26	V-824	Valve (exhaust) ...	Studebaker ...	1932/40	5	6	0	
27	V-857N	Valve (inlet) ...	Do ...	1932/40	3	5	0	
28	V-942L	Valve (exhaust & inlet) ...	Ford Car & Trk. ...	1937/40	2	12	0	
29	V-1056	Valve (exhaust) ...	International ...	1933/39	4	6	0	
30	V-1057N	Valve (inlet) ...	Do ...	1933/39	2	10	0	
31	V-1141N	Ditto ...	Chevrolet Car and Trk ...	1937/40	2	10	0	
32	V-1142N	Ditto ...	Dodge Trk. ...	1937/40	3	5	0	
33	V-1145	Valve (exhaust) ...	Do ...	1937/40	4	10	0	
34	V-1153	Ditto ...	Chevrolet Car & Trk ...	1937	3	1	0	
35	V-1130	Ditto ...	Do ...	1938/40	3	1	0	
36	V-1200L	Valve (exhaust & inlet) ...	Ford Car & Trk. ...	1937/40	0	12	0	
37	VK-84	Engine stem valve key ...	Dodge ...	1937/40	0	10	0	
38	G-127	Valve guide (exh.) ...	Chrysler ... 1930/35 Dodge ... 1930/33		1	9	0	
39	G-128	Valve guide (int.) ...	Chrysler ... 1930/35 Dodge ... 1930/33		1	12	0	
40	G-275	Valve guide (exh. & int.) ...	Ford Car & Trk. ...	1934/40	1	12	0	
41	G-331	Valve guide (int.) ...	Chevrolet Car & Trk ...	1937/40	1	7	0	
42	G-333	Valve guide (exh. & int.) ...	Ford Car & Trk. ...	1937/40	1	12	0	
43	G-341	Valve guide (exh.) ...	Chevrolet Car & Trk ...	1937/40	1	7	0	
44	2519	Crankshaft bearing (Front main) ...	Dodge Trk. ...	1932/41	8	4	0	pair or two halves.
45	2520	Crankshaft bearing (Centre & Inter main).	Do ...	1932/41	8	4	0	,,
46	2569	Crankshaft bearing (Front main) ...	Do ...	1934/41	8	6	0	,,
47	2570	Crankshaft bearing (Centre & Inter main)	Do ...	1934/41	8	6	0	,,
48	2571	Crankshaft bearing (Rear main) ...	Do ...	1934/41	14	1	0	,,
49	2587	Crankshaft bearing (Central main). ...	International Trk. ...	1933/40	5	13	0	,,
50	2588	Crankshaft bearing (Rear main) ...	Do ...	1933/40	7	2	0	,,
51	2589	Crankshaft bearing (Inter main) ...	Do ...	1933/40	6	1	0	,,
52	2836	Crankshaft bearing (Front & Centre)...	Ford ...	1932/38	4	12	0	,,
53	2837	Crankshaft bearing (Rear main) ...	Do ...	1932/38	9	2	0	,,
54	2875	Crankshaft bearing (Front main) ...	Chevrolet ...	1937/42	8	8	0	,,
55	2876	Crankshaft bearing (Centre main) ...	Do ...	1937/42	8	8	0	,,
56	2877	Crankshaft bearing (Rear main) ...	Do ...	1937/39	10	0	0	,,
57	2878	Crankshaft bearing (Inter main) ...	Do ...	1937/42	10	0	0	,,
58	2880	Crankshaft bearing (Front, Centre and Inter main).	Dodge Trk. ...	1937/41	10	2	0	,,

1	2	3	4	5	Rs. a. p.	
59	2881	Crankshaft bearing (Rear main) ...	Dodge Trk. ...	1937/41	17 6 0	pair or two halves.
60	2894	Crankshaft bearing (Front main) ...	International ...	1933/40	11 14 0	„
61	2915	Crankshaft bearing (Rear main) ...	Dodge Trk. ...	1932/41	13 10 0	„
62	2966	Crankshaft bearing (Front and Centre main)	Ford ...	1939/41	4 12 0	„
63	2967	Crankshaft bearing (Rear main) ...	Ford ...	1939/41	10 5 0	„
64	2994	Ditto ...	Chevrolet ...	1940	10 0 0	„
65	2568	Connecting rod bearing (1 upper and 1 lower.)	Dodge Trk. ...	1934/41	4 13 0	„
66	2585	Ditto ...	International Trk. ...	1937/40	5 1 0	„
67	2864	Ditto ...	Oldsmobile ...	1937/41	4 12 0	„
68	2879	Ditto ...	Dodge Trk. ...	1937/40	5 6 0	„
69	289	Ditto ...	Ford Car and Trk. ...	1937/39	10 5 0	„
70	297	Ditto ...	Do ...	1939/40	10 5 0	„
71	2975	Ditto ...	Ford Trk. ...	1939/40	10 5 0	„
72	3200	Ditto ...	Ford Car and Trk. ...	1940	10 5 0	„
73	PC-11	Water pump complete ...	Dodge ...	1935/41	36 8 0	
74	PC-21R	Ditto ...	Chevrolet ...	1937/38	29 1 0	
75	PC-27	Ditto ...	G.M.C. ...	1937/38	41 9 0	
76	PC-33	Ditto ...	Chevrolet ...	1939/40	29 1 0	
77	PC-40	Ditto ...	Dodge Trk. ...	1936/38	55 14 0	
78	PC-43	Ditto ...	Chevrolet ...	1941/42	29 1 0	
79	PA-2	Water pump shaft and impeller assembly.	Ford ...	1932	8 0 0	
80	PA-121	Ditto ...	Do ...	1933/36	3 14 0	
81	PA-148	Ditto ...	Chevrolet ...	1937 38	6 10 0	
82	PA-167	Ditto ...	International ...	1937 39	6 15 0	
83	PA-168	Ditto ...	Do ...	1936/37	10 5 0	
84	PA-181	Ditto ...	Chevrolet ...	1937/38	6 10 0	
85	PA-110	Water pump repair kit ...	Ford ...	1928/31	11 7 0	
86	PA-112	Ditto ...	Do ...	1932	11 11 0	
87	PA-117	Ditto ...	Dodge ...	1933/40	12 14 0	
88	PA-143	Ditto ...	Ford ...	1933/36	6 6 0	
89	PA-153	Ditto ...	Do ...	1937/40	6 10 0	
90	PA-164	Ditto ...	Do Trk. ...	1937/40	17 10 0	
91	PA-166	Ditto ...	International ...	1937/40	11 2 0	
92	PA-199	Ditto ...	Dodge Trk. ...	1936/38	36 5 0	
93	PA-200	Ditto ...	Willys ...	1933/38	18 15 0	
94	PA-202	Ditto ...	Dodge ...	1938/41	22 12 0	
95	PA-204	Ditto ...	Chevrolet ...	1937/38	17 15 0	
96	PA-217	Ditto ...	Oldsmobile ...	1937/40	23 2 0	
97	PA-220	Ditto ...	Chevrolet ...	1939/40	17 15 0	
98	PA-235	Ditto ...	Willys ...	1935/41	21 0 0	
99	PA-275	Ditto ...	Chevrolet ...	1941	17 15 0	
100	PS-187	Water pump shaft ...	Graham ...	1936/37	19 2 0	
101	PS-194	Ditto ...	Ford ...	1937/41	13 8 0	
102	PS-199	Ditto ...	Graham ...	1937	18 1 0	
103	PS-211	Ditto ...	Chevrolet ...	1937	11 11 0	
104	PS-216	Ditto ...	Do ...	1938/40	11 11 0	
105	PS-220	Ditto ...	Studebaker ...	1939/40	13 1 0	
106	PS-228	Ditto ...	Chevrolet ...	1941	11 11 0	
107	PL-167	Water pump impeller ...	International ...	1937/40	4 3 0	
108	PL-175	Ditto ...	Oldsmobile ...	1936/37	3 8 0	
109	PL-190	Ditto ...	Dodge ...	1937/40	3 3 0	
110	PK-1	Water pump packing unit ...	Ford ... 1928/32 International ... 1936/37		1 7 0	
111	M-110	Water pump seal ...	Dodge Trk. ...	1932/41	2 7 0	
112	M-153	Ditto ...	Chevrolet ...	1937/38	2 12 0	
113	M-170	Ditto ...	Ford ...	1933/41	3 1 0	
114	M-204	Ditto ...	International ...	1937/40	5 4 0	
115	M-218	Ditto ...	Dodge Trk. ...	1938/41	2 10 0	
116	M-270	Ditto ...	Chevrolet ...	1937/42	1 14 0	
117	M-270R	Ditto ...	Do ...	1938/42	2 3 0	
118	M-375	Ditto ...	Oldsmobile ...	1937/40	3 1 0	
119	M-531	Water pump thrust bearing seal ...	Dodge ...	1938/41	0 4 0	
120	KA-5	King bolt assembly ...	Chevrolet Trk. ...	1931/40	11 14 0	
121	KA-9	Ditto ...	Ford Trk. ...	1935/37	29 1 0	
122	KA-15	Ditto ...	Dodge ...	1935/37	15 5 0	
123	KA-28	Ditto ...	Chevrolet ...	1937/40	13 5 0	
124	KA-32	Ditto ...	Ford Car ...	1937/40	14 8 0	
125	KA-36	Ditto ...	Willys ...	1933/36	18 2 0	
126	KA-37	Ditto ...	Do ...	1937/40	18 2 0	
127	KA-41	Ditto ...	Dodge ...	1932/37	27 6 0	
128	KA-61	Ditto ...	Chrysler ...	1935/39	31 4 0	
129	KA-70	Ditto ...	Ford Trk. ...	1938/40	26 3 0	
130	KA-101	Ditto ...	Dodge Trk. ...	1940/41	22 14 0	

1	2	3		4		5	6			
							Rs.	a.	p.	
131	K-1023	King bolt	...	International	...	1929/37	5	13	0	
132	K-1038	Ditto	...	Chrysler	...	1930/33	6	10	0	
133	KB-9842	King bolt bushing	...	Dodge Car an Trk.	...	1931/39	1		0	
134	KB-10233	Ditto	...	International	...	1929/37	0	13	0	
135	KB-10381	Ditto	...	Dodge Car	...	1933	1	3	0	
136	SB-269	Spring bushing	...	Buick	...	1931	2	0	0	
137	SB-309	Ditto	...	Dodge Trk.	...	1932/38	1	12	0	
138	S-1130	Spring bolt (Rear)	...	Chevrolet	...	1936/38	2	1	0	
139	S-1132	Ditto	..	Studebaker Trk.	...	1935/39	3	14	0	
140	S-1150	Ditto (Front and Rear)	...	Ford Trk.	...	1932/37	3	1	0	
141	S-1156	Ditto (Rear)	...	Chevrolet Trk.	...	1937/40	2	12	0	
142	S-1159	Ditto	...	Dodge Trk.	...	1932/38	2	7	0	
143	S-1160	Ditto	...	Do	...	1932/38	3	3	0	
144	S-1168	Ditto (Front)	...	Chevrolet Trk.	...	1937/40	1	10	0	
145	S-1179	Ditto	...	International	...	1937/40		8	0	
146	S-1180	Ditto (Rear)	...	Do	...	1937/40	2	5	0	
147	S-1203	Ditto (Front)	...	Chevrolet Car	...	1936/38	1	14	0	
148	S-1205	Ditto (Rear)	...	Dodge Car	...	1934/36	2	0	0	
149	S-1210	Ditto (Front)	...	Studebaker Trk.	...	1936/40			0	
150	S-1222	Ditto	...	Dodge Car	...	1937/41			0	
151	S-1224	Ditto (Rear)	...	Chevrolet Trk.	...	1937/38	1	15	0	
152	S-1239	Ditto (Front)	...	Dodge Trk.	...	1937/41	2	3	0	
153	S-1249	Ditto (Rear)	...	Hudson	...	1937/39	2	5	0	
154	S-1251	Ditto (Front and Rear)	...	Ford Trk.	...	1938/40	2	5	0	
155	FA-10	Knuckle support pin assembly	...	Dodge Trk.	...	1939	16	15	0	
156	UA-10	Silent U-shackle bolt	...	udebaker	...	1934/36	8	0	0	
157	UA-12	Ditto	...	Hudson	...	1933/39	8	0	0	
158	UA-16	Ditto	...	Studebaker	...	1934/36	7	13	0	
159	UA-17	Ditto	...	Oldsmo	...	1933/36	7	15	0	
160	UA-30	Ditto	...	Buick	...	1934/35	7	11	0	
161	UA-35	Ditto	..	Studebaker	...	1937/39			0	
162	UA-38	Ditto	...	Dodge	...	1936/38			0	
163	UA-42	Ditto	...	Plymouth	...	1937/39	7	15	0	
164	UA-43	Ditto	...	Dodge	...	1936/39	7	15	0	
165	UA-45	Ditto	...	Hudson	...	1937/39	7	15	0	
166	UA-47	Ditto	...	Do	...	1937/39	7	15	0	
167	UA-48	Ditto	...	Do	...	1937/39	7	15	0	
168	UA-57	Ditto	...	Desoto	...	1937/39	7	15	0	
169	UA-58	Ditto	...	Chrysler	...	1939/40	7	15	0	
170	UA-59	Ditto	...	Dodge	...	1939/40	7	15	0	
171	UB-5	Silent U-shackle bushing	...	Do	...	1930/31	2	3		
172	UB-11	Ditto	...	Desoto	...	1928/32				
173	UB-16	Ditto	...	Chrysler	...	1934/36	2	8	0	
174	UB-17	Ditto	...	Buick	...	1936	2	1	0	
175	UB-18	Ditto	...	Chrysler	...	1936	2	8	0	
176	UB-19	Ditto	...	Nash	...	1939/41		3	0	
177	UB-21	Ditto	...	Plymouth	...	1937/38			0	
178	UB-24	Ditto	...	Dodge	...	1936/41	2	0	0	
179	ES-23	Tie rod socket (for R and L rods	...	Desoto	...	1937/39	2	0	0	
180	RS-26	Ditto	...	Chevrole	...	1937/40	20	4	0	Pair.
181	RS-29	Ditto	...	Do	...	1937/40	15	10	0	,,
182	ES-60	Ditto (for Right rod)	...	Do	...	1937/40	14	10	0	,,
183	ES-61	Ditto (for Left rod)	...	Chrysler	...	1937/40	20	6	0	,,
184	ES-64	Ditto (for R and L rods)	...	Do	...	1937/40	20	6	0	,,
185	ES-65	Ditto	...	Ford Trk. and Car	...	1935/40	11	4	0	,,
186	ES-98	Ditto	...	Ford Trk.	...	1936/39	15	1	0	,,
187	ES-106	Ditto	...	Do	...	1940	14	3	0	,,
				Studebaker	...	1940	15	1	0	,,

PA-110.—Water Pump Repair Kit-consists of one each : PA-1 Shaft and Impeller Assembly; one PB-1 Rear Bushing ; one PN-100 Packing nut ; one PK-1 Packing Unit ; one M-3 Pulley Key ; one M-15 Brass Impeller Washer; two M-48 Bearing Felts ; one M-49 Bearing Felt Retainer; two M-50 Steel Bearing Washers; one M-51 Shaft Nut; one M-53 Front Bearing and Sleeve and one M-281 Gasket.

PA-112.—Water Pump Repair Kit-consists of one each : PA-1 Shaft and Impeller Assembly ; one PB-1 Rear Bushing ; one PN-100 Packing Nut ; one PK-1 Packing Unit ; one M-3 Pulley Key ; two M-18 Impeller Thrust Washer ; two M-48 Bearing Felts ; two M-49 Bearing Felt Retainers ; two M-50 Steel Bearing Washers ; one M-51 Shaft Nut ; one M-53 Front Bearing and Sleeve and one M-282 Gasket.

PA-117.—Water Pump Repair Kit-consists of one each : PA-89 Shaft, Impeller and Complete Seal Assembly ; PB-186 Front Bushing ; PB-187 Rear Bushing ; M-31 Pulley Hub Pin ; M-52 Thrust Washer ; M-181 Bushing Pin ; M-288 Cover Plate Gasket and M-289 Pump-to-Block Gasket ; M-290 Cover Plate Gasket and M-291 Pump-to-Block Gasket; M-292 Elbow Gasket and M-293 Copper Washer.

PA-143.—Water Pump Repair Kit-consists of one each PA-140 Shaft and Impeller Assembly ; MA-19 Seal Kit ; M-58 Pulley Felt ; M-59 Felt Retainer and two PB-155 Bushings.

PA-153.—Water Pump Repair Kit-consists of one each : PS-189 Shaft ; PL-173R Impeller with M-170 Complete Seal ; PB-250 Bushing ; M-17 Pulley Thrust Washer and M-306 Gasket.

PA-164.—Water Pump Repair Kit-consists of one each : PS-194 Shaft and Bearing ; PL-173R Impeller with M-170 Complete Seal and M-306 Gasket.

PA-166.—Water Pump Repair Kit-consists of one each : PA-167 Shaft and Impeller Assembly ; PB-270 Front Bushing ; PB-271 Rear Bushing ; PN-138 Packing Nut ; PK-1 Packing Unit ; M-3 Pulley Hub Key ; M-199 Thrust Washer and M-317 Gasket.

PA-199.—Water Pump Repair Kit-consists of one PA-139 Shaft Impeller and Complete Seal Assembly ; two M-246 Bearing and Cup Assemblies ; one PB-231 Rear Bushing one M-31 Pulley Hub Key ; one M-290 Cover Plate Gasket one M-291 Pump-to-Block Gasket ; one M-292 Elbow Gasket

one M-344 Bearing Retainer Gasket; M-345 Oil Seal Assembly and M-346 Oil Seal Felt.

PA-200.—Water Pump Repair Kit-consists of PA-93 Shaft and Impeller Assembly; M-247 Bearing; PB-61 Rear Bushing; PN-2 Packing Nut; PK-1 Packing Unit; M-3 Pulley Key; M-31 Bushing Pin; M-347 Grease Retainer Assembly; M-348 Gasket; M-349 Shaft Nut and M-350 Washer.

PA-202.—Water Pump Repair Kit-consists of one each; PS-209 Shaft and Bearing Assembly; PL-190 Impeller; MA-18 Seal Kit and M-338 Water Thrower. (MA-18 consists of one each; M-218 Complete Seal; M-31 Pulley Hub Pin; M-290 Cover Plate Gasket; M-291 Pump-to-Block Gasket and M-339 Bearing Lock Ring).

PA-204.—Water Pump Repair Kit-consists of one each; PS-211 Shaft and Bearing; PL-191 Impeller and MA-6 Seal Kit. (MA-6 consists of one each; M-270 Complete Seal; M-271 Bearing Retainer; M-302 Pump-to-Block Gasket and M-303 Cover Gasket).

PA-217.—Water Pump Repair Kit-consists of one each; PS-191 Shaft and Bearing Assembly; PL-175 Impeller; MA-25 Seal Kit and M-374 Pulley Hub. (MA-25 consists of one each; M-375 Complete Seal; M-215 By-Pass Seal; M-307 Bearing Retainer; M-372 Cover Plate Gasket; M-373 Pump-to-Block Gasket and M-381 Bearing Shield).

PA-220.—Water Pump Repair Kit-consists of one each; PS-216 Shaft and Bearing; PL-191 Impeller and MA-6 Seal Kit. (MA-6 consists of one each: M-270 Complete Seal; M-271 Bearing Retainer; M-302 Pump-to-Block Gasket and M-303 Cover Gasket).

PA-235.—Water Pump Repair Kit-consists of one each; PS-193 Shaft and Bearing Assembly; PL-199 Impeller and MA-38 Seal Kit. (MA-38 consists of one each; M-460 Complete Seal; M-307 Bearing Lock Wire and M-459 Gasket.)

PA-275.—Water Pump Repair Kit-consists of one each: PS-228 Shaft and Bearing; PL-191 Impeller and MA-43 Seal Kit. (MA-43 consits of one each: M-270 Complete Seal; M-271 Bearing Retainer; M-583 Pump-to-Block Gasket and M-584 Cover Gasket.)

D. RUTNAM, Joint Secy.

With reference to sub-rule (1) of rule 119 of the Defence of India Rules, the Central Government is pleased to direct that the above order shall be published in the *Gazette of India* and a notice of the above order giving reference to the publication in the *Gazette of India* shall also be published in the official Gazette of each Province, and a Press Note giving an indication of the nature of the order and the fact of its publication in the *Gazette of India* shall be issued.

D. R. RUTNAM, Joint Secy

New Delhi, the 4th September 1945.

No. 52-LPC. (6) 45-Wagner.—In exercise of the powers conferred by paragraph (b) of sub-clause (1) of clause 4 of the Motor Vehicle Spare Parts Control Order, 1944, the Central Government is pleased to direct that with effect on and from the 25th September 1945, the following amendments shall be made in the Notification of Government of India in the War Transport Department No. 52-LPC (6)/45-Wagner dated the 1st June 1945, namely:—

In the Schedule annexed to the said notification,—

(a) Against Serial No. 44, for the existing figures in the last column, the following shall be substituted namely:—

"4 10 0";

(b) Against Serial No. 185, for the existing figures in the last column, the following shall be substituted namely:—

"3 8 0"; and

(c) After the entry relating to Serial No. 198 the following entries shall be added, namely:—

S. No.	Part No.		Description			Maximum retail sale price		
						Rs.	a.	p.
"199	FC	4844	Brake hose	...	...	5	15	0
200	FC	5994	W. C. boot	...	...	0	14	0
201	FD	6353	W. C. cup	...	...	1	5	0
202	FC	7092	W. C. piston	...	...	2	14	0
203	FC	7094	W. C. boot	...	...	1	2	0"

K. G. MITCHELL, Addl. Secy.

With reference to sub-rule (1) of rule 119 of the Defence of India Rules, the Central Government is pleased to direct that the above order shall be published in the *Gazette of India*, and a notice of the above order giving reference to the publication in the *Gazette of India*, shall also be published in the Official Gazette of each Province, and a Press Note giving an indication of the nature of the order and the fact of its publication in the *Gazette of India* shall be issued.

3379 K. C. MITCHELL, Addl. Secy.

DEVELOPMENT SECRETARIAT

Dated 27th November 1945.

No. D. 4171—I. & C. 203-45-3. It is hereby notified for the information of the public that the acquisition of 1 acre and 21 guntas of land out of Survey No. 174—2 and 175, of Bagepalli village for the construction of a tile factory sanctioned by Government in their Order No. D. 8844-6—I. & C. 543-44-4. dated 23rd June 1945, is withdrawn since it is not required for the purpose originally intended.

3473 C. E. NORONHA, *Dev. Secy.*

Dated 26th November 1945.

No. SD. 3302—C. 96-45-7. In exercise of the powers conferred by sub-rule (2) of Rule 81 of the Defence of India Rules as applied to Mysore and in partial modification of Notification No. CS. 4556, dated 12th December 1942, the Government of His Highness the Maharaja are pleased to direct that no person shall with effect from the date of this order transport horsegram by rail, road or otherwise from any place in the State to any place outside the State.

3479

Dated 27th November 1945.

No. S. D. 3271—C. 96-45-5. In exercise of the powers conferred by sub-rule (2) of Rule 81 of the Defence of India Rules as applied to Mysore and in supersession of the Notification No. S. D. 17705-15, dated 13th May 1943, the Government of His Highness the Maharaja are pleased to direct that no person shall, with effect from the date of this order, transport cotton seed by rail, road or otherwise from any place in the State to any place outside the State.

3477

Dated 27th November 1945.

No. S. D. 3288—C. 96-45-6. In exercise of the powers conferred by sub-rule (2) of Rule 81 of the Defence of India Rules as applied to Mysore and in partial modification of Notification No. S. D. 6718—C. 36-43-80, dated 4th April 1944, the Government of His Highness the Maharaja are pleased to direct that no person shall, with effect from the date of this order transport groundnut seed by rail, road or otherwise from any place in the State to any place outside the State.

3478 C. E. NORONHA, *Dev. Secy.*, (Food Supplies).

REVENUE SECRETARIAT

Dated 24th November 1945.

No. L. 4146—I. M. 3-45-5. In exercise of the powers conferred by Section 5 of the "Act for the Prohibition of Beggary 1944", the Government of His Highness the Maharaja are pleased to constitute a Central Relief Committee consisting of the following members for administering the Beggar Relief Scheme in the State:—

1 The Director of Public Health in Mysore, Bangalore
2 The Senior Surgeon in Mysore, Bangalore
3 The Chief Medical Officer, Women's Hospitals in Mysore, Bangalore
4 The Director of Industries and Commerce in Mysore, Bangalore
5 The Director of Agriculture in Mysore, Bangalore
6 The Director of Public Instruction in Mysore, Bangalore
7 The President, Municipal Council, Civil and Military Station, Bangalore.
8 The President, Municipal Council, Bangalore City
9 The President, Municipal Council, Mysore City
10 *Dharmaprakasa Rao Bahadur* Devarao Shivaram
11 *Dharmaprakasa* Mr. K Kuppaswamy Naidu
12 Mr. N Balakrishniah, B.A., LL.B.
13 Captain *Rao Bahadur* A Thangavelu Mudaliar
14 *Khan Saheb* Mohamed Sheriff
15 Mr. Ramachandra Rao, Secretary, Ashakta Poshakasabha, Bangalore.
16 *Najmut-Tujjar* Mr. A R A Basith
17 *Moin-ul-Vizarath* Mr. A K Syed Taj Peeran, B.A.
18 Mr. C Narayanaswamy Naidu, B.A., B.L., Retired Secretary to Government, Law Department and Legal Remembrancer to Government.

(2) Mr. C. Narayanaswamy Naidu, B.A., B.L., is appointed as the Chairman of the Committee. Separate orders will issue in regard to the appointment of a Secretary to the Committee.

(3) The term of Office of the members will be two years.

3463